Certificate of Location of Government Corner

ID#: 741109 **Description:** SEC CEN 11 74 **Date Set:** 2/1/1978 **County:** Olmsted

Section: 11 **Township:** 107N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

5/8" pipe w/cap RLS #6507

Reference Ties:

The monument is at the surface
This corner is located by GPS reference stations "Mallard B & C"

Corner History:

1-3-1900 Robert Fraser, County Surveyor, (Book A, Pages 646-652, Survey No. 582 and Field Book #15, Pages 3-20) corner run in by Thomas Hunter. Pioneers claim it came near stump, some trees blazed. Set Burr Oak stake and 2"x18"x30" stone at intersecting quarter lines. The corner falls 2' from stump. RPs - Jack Oak N 5 links (3.30'), Jack Oak S9°W 23-1/2 links (15.51'). 1/16th North set stake midway and on line at 19.75-3/4 chains (1304.00') to North 1/4. 1/16th East set stake midway and on line at 19.97-1/4 chains (1318.19') to East 1/4. RPs - 2" Burr Oak N14°E 22 links (14.52'), 10" Jack Oak S69°E 15-1/2 links (10.23').

10-3-1901 William Fraser, County Surveyor, (Book A, Pages 646-652, Survey No. 582, Caption) 1/16th South set stone midway and on line at 19.89 chains (1312.74') to South 1/4.

11-13-1939 John Kerr, County Surveyor, (Book 16, Page 60) found stone. Set 1/2" steel shaft with gear on west side of stone. RPs - Oak tree N 3.3', 16" Oak SSE 30'.

8-1975 McGhie & Betts used computed center at intersecting quarter lines for Buckthorn Subdivision. Based on their computation, the computed center falls 4.67' East and 1.61' South of stone. 1/16th South computed sixteenth falls 4.30' East and 0.88' North of stone.

2-1-1978 Thomas Taylor set 5/8" pipe w/cap RLS #6507 at intersecting quarter lines for Oak Meadow First Subdivision.

4-4-1990 County Surveyor found stone with flat iron beside and 5/8" pipe w/cap #6507. The 5/8" pipe falls 4-1/2' easterly of stone with fiberglass post beside pipe.

7-1-1991 County Surveyor used 5/8" pipe w/cap for Olmsted County Highway Right of Way Plats No. 70 & 71.

1-7-1999 GGG used computed center at intersecting quarter lines.

5-9-2000 GGG found and used monument.

12-16-2003 County Survey Crew found 5/8" pipe w/cap at the surface in good condition and measured its position using GPS. Also found flat iron 4.5' west.

9-10-2004 GGG found and used monument.

11-1-2005 GGG found and used 5/8" pipe w/cap RLS #6507 for Oak Meadow Second Subdivision.

10-23-2012 Joel Thoreson, County Surveyor, recommends using the monumented center of section based on historical use of this position.