Certificate of Location of Government Corner

ID#: 741504 **Description:** 1/4 SEC COR 15 22 74 **Date Set:** 11/24/93 **County:** Olmsted

Section: 15 **Township:** 107N **Range:** 14W **Monument Description:** 4 chisel marks on manhole ring

Reference Ties:

The manhole falls in centerline of 41st St NW and in centerline of 18th Ave NW
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: M.Karrick; 40.0 set temp 1/4 section post west on true line between sections 15-22. 40.0 set 1/4 section post in mound with trench, pits, charred stake, and planted osage orange seeds NE & SW.

5-1870 R. Perry Pg.178 No.189; Corner gone, reset 30' from point in Boardmans fence he avers correct fence south.

5-1912 D. Williams Pg.210 B; found boulder stone with old stake beside it. 16 East set limestone, 16 south set limestone.

1941 J. Kerr - Found boulder, recorded, meas. west 2641.5.

11-1961 J. Kerr - Rps. to corner when set as CIM now gone. RPs-Steel angle fence corner NE 46.23. Sp power pole NW 37.65. Sp guy power pole SW 40.82.

1968 Bk.340 county highway department RPs to 1/16 corner south, new 22. Iron pipe in place in centerline 18th Ave. RPs- spike in street light pole NW
46.59, spike and disc in pp SSW 123.98.

6-2-1981 County Surveyor found chisel knotches on manhole ring, made intersect. Checked tie to Hyd (SW) checked 42.93' instead of 43.03. Hyd. is not the same hyd as tie. Other ties now gone.

6-18-1992 County Surveyor set straddle nail after constr. of road. Instrument at 18&43 < Rt. 3810 to straddle nail 0º 26'43". To straddle nail VA 89 25 46, SL 1148.34 HD 1148.28. Previous dist. 1149.40 (Move 1.12').

11-24-1993 County Surveyor laid out corner location from traverse ties & set straddles. Found marks on MH ring that were no longer good, also "+" on cover. Put marks on ring for intersect. of final corner.

11-12-1997 County Surveyor verified chisel marks on ring were there and correct. Chiseled deeper.

5-10-2002 Mn/DOT Survey Crew found chisel marks on manhole ring in good condition.

8-5-2002 County Surveyor found chisel marks on manhole ring in good condition.

8-16-2007 County Surveyor found chisel marks on manhole ring in good condition.