Certificate of Location of Government Corner

ID#: 741505 **Description:** SEC COR 15 16 21 22 74 **Date Set:** 7/12/2006 **County:** Olmsted

Section: 15 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 3' north of centerline of WBL of 41st St NW and 11' west of centerline of frontage road south
Center of stop light base NW 47 1/2'
This corner is located by GPS reference stations "Best & Broad"

Corner History:

Gov't Notes - M. Karrick 80.00 set post for corner to sec 15-16-21-22 erected mound, trench, pitts, charred stake, & Osage Orange seeds at each angle.

1941 J. Kerr B.24 P.78 S.22 Sam Allen Found broken crock ' below road surface and hole in clay below with piece of china dish where original stake was driven into .35' to row of trees on s. side of road, 32' to row tree stumps on n. side of road . Set 11/4"x5' iron pipe with 7/8" shaft inside as corner. Center cottonwood N 73.3 Center 24" Ash NE 47.0 Meas. east to 1/4 15-22 2641.5 S 5335.4.

8-1951 J. Kerr B. 52 P. 40, Meas. south 5336.0

7-1959 J. Kerr B. 79, P. 36, run line north to 1/4 15-16 set point at M&L. 1314.13 for line west across pavement point likely temp.

9-1969 J. Kerr rods set north 33.0 & 133.0 found when corner referenced (road building).

4-4-1984 County Surveyor found CIM down 9" in blacktop. Set 5/8" rod over CIM and packed in Bearing Tree. Broke head off CIM.

7-26-2002 County Surveyor found corner destroyed due to TH 52 and 41st St NW overpass construction.

7-12-2006 County Surveyor set 1" square pipe w/cap from computed coordinates at surface.

12-13-2006 County Surveyor found 1" square pipe w/cap down 0.4' with cap gone and top portion milled off. Set new cap on pipe.