Certificate of Location of Government Corner

ID#: 741805 **Description:** W SEC COR 18 19 74 **Date Set:** 3/13/2002 **County:** Olmsted

Section: 18 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 130' NE of centerline of CSAH 4 on curve
Post w/sign 1' east
This corner is located by GPS reference stations "Leqve A & Goulet"

Corner History:

Gov't Notes: 80.00 Sec. post. & drove charred stake corner to 13-18-19-24 Black Oak 6 D 15 W238, Burr Oak 14 D 54 E160.

10-1877 T. Hunter P. 321, No. 315 corner missing - Stake still in mound set stone 18"x7"x10" running to point. 16 south set quarried stone 3"x5"x18" M&L 19.95. Meas. east 338.25 to corner fence post placed in center mound by Mr. Nooman in place of pole set by Fred Pastier when he broke the ground.

7-1890 Thomas Fraser, P. 445, No. 430 Found 1/16 stone so. & 1/4 cor. so. placed by Hunter.

1936 County Highway Department Book #89 Pg. 76 set square iron nail 1315.5 north of 1/16 corner found.

9-1966 J. Kerr - Found stone. Placed CIM over 11/4"x23" pipe with org. stone & 2x2 County hub near at .55' west. Nail in hub on N. side 14" Cedar Pine SE 62.35. Corner lies 3' from W. edge traveled road. 30' from east edge of blacktop on curve due west.

7-14-1987 County Surveyor found CIM OK. Set sign and post 1' east.

3-4-2002 County Surveyor found CIM down 0.2' leaning Westerly.

3-13-2002 Removed CIM and found 1 1/4" pipe down 2.1' in good condition. Removed 1 1/4" pipe and set 6' telspar w/CI cap at surface at 1 1/4" pipe location.