# Certificate of Location of Government Corner

**ID#:** 742406 **Description:** 1/4 SEC COR 23 24 74 **Date Set:** 12/11/97 **County:** Olmsted

**Section:** 24 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe/cap RLS #15809

**Reference Ties:**

The corner falls 2.4' NE of center of water shut off casting and in centerline East River Road
CN&D in PP #34540 up 1.5' NE 42.54'
Property corner pipe E 33.00'
This corner is located by GPS measurement

**Corner History:**

Gov't Notes Mike Karrick - 1854 40.00 Set quarter section post. Burr Oak 12" S86ºW 286 lks. Burr Oak 12" N78ºW 174 lks.

5-1874 Tom Hunter Pg. 246 No. 247 Found stone in center of road which lined with the fence East. Bearing trees gone. 1/16 West set stake M&L 19.96 3/4. 1/16 South set temp. stake M&L 19.731/2. 1/16 North set stone 2"x7"x13" M&L 19.791/2.

8-1876 Tom Hunter Pg. 303 No. 298 Found boulder stone. 1/16 East set stake M&L 20.16. 1/16 Center NW1/4 24 set stone at intersecting lines.

1937 Co. Highway Dept. Found 4"x6"x18" boulder 12" deep in line fence west.

3-1966 John Kerr, Co. Surveyor Found 1"x12" rod over original boulder and set a C.I.M. which fell in the center of the road and in-line with the fence east.

8-12-1983 Roger Brand, Co. Surveyor Dug below C.I.M. and found rust hole of 1"x12" iron prior to sewer & water installation. Took new references.

10-15-1986 County Surveyor Set cast iron cap on telspar pipe from references taken before construction. Nail & disc in light pole N.E. 41.01. Nail & disc in power pole N.E. 42.51. Nail & disc in power pole S.W. 36.25. 1/2" rod east 36.25. Corner 1' east of centerline E-W road and 12' south of centerline of gravel road west.

7-30-1993 County Surveyor-Referenced & removed the cast iron cap on telspar pipe for road construction & took new references.

8-7-1996 County Surveyor set a P.K. nail from the 1993 ties & checked the property corner 33.00 feet east.

12-11-1997 County Surveyor set 1" square pipe with cap at the P.K. location. Corner falls 2..4' N.E. of center of water shut off casting.

12-16-1997 McGhie & Betts Found 1" square monument with Aluminum cap in center line road.

12-11-2003 County Surveyor found 1" square pipe w/cap at surface in good condition. PP's to the NW & SW are gone.