Certificate of Location of Government Corner

ID#: 742605 **Description:** SEC COR 26 27 34 35 74 **Date Set:** 8/18/92 **County:** Olmsted

Section: 26 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of 14th St NW, 18' east of centerline of 11th Ave NW south, and 13 1/2' NE of centerline of 11th Ave NW
Center top nut fire hydrant SW 108.40'
SW corner square fence post NNE 60.44'
SW corner concrete pad of signal box SE 53.32'
This corner is located by GPS measurement

Corner History:

6-1853 Gov't Notes Michael Karrick, Deputy Surveyor North between sections 34 and 35. 80.00 Set post in mound with trench, pits, charred stake and planted osage orange seeds at each angle for corner to sections 26-27-34-35.

1951 Ken McGhie, a surveyor, found stone down .6' with pipe riser.

1967 City of Rochester: 5" x 5" stone down 1.9'.

9-23-1974 Roger Brand, County Surveyor, dug with jackhammer and found limestone 3 1/2" x 5" on top down 2.1' in bit. surface intersection of 14th St and 11th Ave NW, Rochester. Set 1/2" rods on north and south sides of stone with C.I.M. above stone flush with surface.

10-17-1986 County Surveyor found C.I.M. down 4" in new blacktop, (1974) ties did not fit well.

7-2-1990 County Surveyor set P.O.T. to quarter corner 26, 35 east 169.49' before construction.

10-16-1990 County Surveyor dug out stone, it was a cut stone 4" x 5" x 16" with a cross and drill hole on top.

6-18-1992 County Surveyor set on P.O.T. set 7-2-90, found P.K. nail at location of corner correct.

8-18-1992 County Surveyor set 1" square pipe/cap in place of P.K. nail.

8-18-1992 Edward Kuisle prepared an unsigned certificate of location for this corner.

1-8-1997 MN/DOT survey crew found 1" square pipe w/cap in good condition.

1-8-1997 MN/DOT note from corner maintenance record: This corner was recovered and ties were verified and/or resstablished if not in place.

3-6-2000 Mn/DOT survey crew found 1" square pipe w/cap in good condition and took additional reference ties.

8-2-2002 County Surveyor found 1" square pipe with cap at surface and in good condition.

9-14-2007 County survey crew found 1" square pipe w/cap at surface in good condition.

8-4-2010 County survey crew found 1" sq. pipe with cap down 0.2' in good condition.