Certificate of Location of Government Corner

ID#: 742705 **Description:** SEC COR 27 28 33 34 74 **Date Set:** 8/29/02 **County:** Olmsted

Section: 27 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls West of a bituminous parking lot and SW of Waters Instruments 2411 building and 96' North of centerline of 7th St NW
Most SW'ly corner 2411 building NE 131.38'
Pk nail in East side PP (up 3') SW 87.60'
Center top nut fire hydrant SE 77.50'
Post w/sign 2' north
County Survey Disk in PP #11077 SW 87.45'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M. Karrick, 80.00 set post for corner to sect. 27-28-33-34 in mound with trench, pitts, charred stake & Osage Orange seeds at each angle.

5-26-1965 John Kerr found 1" square iron in N-S fence line. Set CIM over 1-1/4" x 20" pipe.

3-15-1979 County Surveyor ties out CIM.

10-23-1986 County Surveyor, top section of CIM broken off but remainder standing OK Cor. 3'± N of gas pipe.

11-20-1987 County Surveyor found CIM used in CSAH 22 R/W survey.

1-8-1997 MN/DOT survey crew found CIM with head broken off.

1-8-1997 MN/DOT survey crew notes of corner location: On May 26, 1965 John Kerr prepared an unsigned certificate of replacing section corner for this corner. On Jan 8, 1997 this corner was recovered and ties were verfied and or reestablished if not in place.

3-5-2002 MN/DOT survey crew found CIM with top broken off.

8-29-2002 County Surveyor found CIM down 0.3' with head broken off, removed CIM found 1" pipe down 2.5', removed pipe. Set 6' telspar w/CIC at surface. CSD in PP #11077 87.45' SW and 77.50' SE to top of nut of hydrant. Set sign & post 2.0' North.