Certificate of Location of Government Corner

ID#: 742806 **Description:** 1/4 SEC COR 28 29 74 **Date Set:** 8/9/2012 **County:** Olmsted

Section: 28 **Township:** 107N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #42638

Reference Ties:

The monument is down 0.1'
The corner falls 13 1/2' North of back of curb of median in 19th St. NW and 194' East of centerline of northbound lane of CSAH 22
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, M. Karrick 40.00 set 1/4 section post in mound with trench, pitts, charred stake & Osage Orange seeds NE & SW.

4-1858 T. Hunter, P.52 No. 75 used corner for line west, meas. west 38.86 to center 29, then from center west 19.91 M&L, no other information at this time.

11-1863 P.C. Compton Pg. 78 No. 117, shows 1/4 cor. used to set center sec. 28 at intersecting lines set 1/16 east M&L to center sec. 28.

1950's McGhie & Betts Set 1" rod at W1/4 28 at 1729.0 No. of centerline of R.R. & in line of fence running south. Tied To: Spike in fence post NW 22.9, meas. east to cen. 28 to 5/8" rod found & used as Cen. 28 - set 1/16 East (5/8" rod).

1-15-1974 County Surveyor set short (10") CIM over other CIM, after surfacing E-W Road, top of CIM was down about 13" set short CIM with top down 2".

11-20-1989 County Surveyor dug with jackhammer, found CIM.

7-10-1997 County Surveyor found CIM in good condition and referenced before 19th Street construction

7-14-1998 County Surveyor set P.K. Nail from reference and traverse.

9-30-1998 County Surveyor set 1" sq. pipe w/cap #15809 over P.K. nail.

2-12-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

6-19-2012 County survey crew found 1" square pipe destroyed due to construction of 19th Street NW

8-9-2012 County survey crew set a 1" square x 2' long pipe with cap #42638 after 19th Street NW construction at previously measured GPS coordinate location.