Certificate of Location of Government Corner

ID#: 743205 **Description:** S SEC COR 31 32 74 **Date Set:** 2/12/2002 **County:** Olmsted

Section: 32 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in open pasture hillside
Spike in 24" Oak ENE 103.4'
West edge of 43" diam. Tile (Spring outlet) ENE 38.2'
Post w/sign 2' West
This corner is located by GPS reference stations "Pasture & 45th Ave SW"

Corner History:

Gov't Notes Set post for corner - Black Oak 8" N 88° W 64 lks., Black Oak 8" N30°E 24 lks., Black Oak 5" S15°W 24 lks., Black Oak 7" S38°E 48 lks.

11-1856 T. Hunter, P. 19 No. 31, 1/16 East 19.71 M&L, 1/16 South 19.73 Then 20.00 to 1/4 cor. 5-6 Rochester, 1/16 North 19.681/2 M&L Bearing Trees (N 701/2° W 721/2 lks.)(S35°E 57 lks.)

3-1902 W. Fraser, P.36 - Found stone corner - used only to set N1/4 6 easting & westing.

12-1921 J. Kerr, P.374 - Found stake & stone with Bearing trees, 18" Oak NE 103.4', 15" tree NW 70.5.

1939 County H.D. stone with 3/4" rod on top. RPs- spike on top of fence post NE 38.7', spike on top of fence post NW 55.3', hub south and north 66'.

10-1963 J. Kerr found stone with help, set CIM over or beside original stone, heavy oak post with hub nailed on S 2.1, Sp 15" hickory North 70.5, Sp 24" Oak ENE 103.4.

6-1974 - Corner hard to locate without tree ties.

4-2-1982 County Surveyor found CIM flush with ground

8-1989 County Surveyor found CIM with broken top. Set sign and post 1' west.

2-4-2002 County Surveyor found CIM w/broken top down 0.5' leaning SE'ly.

2-12-2002 County Surveyor removed CIM and found 3/4" pipe down 1.5'. Set 4' telspar w/CI cap down 0.2' over 3/4" pipe.