Certificate of Location of Government Corner

ID#: 750605 **Description:** W SEC COR 6 7 75 **Date Set:** 8/7/1989 **County:** Olmsted

Section: 06 **Township:** 107N **Range:** 15W **Monument Description:** 5/8" brass plug

Reference Ties:

The corner falls in centerline of CSAH 5 and in centerline of Dodge CR 18 west
County highway disk in PP #51186 SW 61.00'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes John Ball, Deputy Surveyor; North between sections 7 & 12. 80.00chs. Set corner post. RPs-10" black oak N22 1/2°E 238 links, 14" black oak S70 1/2°W 442 links.

12-1892 A.A. Crampton found a limestone set by a former surveyor. Set an iron at the 1/64 north and the 1/16 north.

4-1897 William Fraser (Bk.A Pg.607 No.552) found a stone boulder with a cross cut in the center.

9-1936 Olmsted county highway department (county highway department Bk.84) found a boulder with cross.

11-1946 John Kerr (Kerr Book 32 Pg.43), County Surveyor found a boulder

11-1947 Olmsted county highway department Bk.84 Pg.76; Found boulder with cross, RPS-hub in 30" boxelder SE 83.7', hub in 12" twin oak SW 66.4' telephone pole NW 58.1, 10" oak SW 60.5', fence post NW 68.3', TP NW 58.1', 10" oak SW 60.5'.

11-14-1978 Olmsted County Surveyor dug and found a 12"x14"x21+" boulder with cross dwon 20". Drove a 1 1/4"x16" shaft in a stake hole found on the west side of the stone. A 1 1/4" shaft (removed) found at the surface of the road was 1.85 west and .85 north of the stone.

11-16-1978 Olmsted County Surveyor set a CIC on a 16" square pipe over the boulder. We searched with the electronic dip needle at the 1/64 north and the 1/16 north, but didn't find anything. Both corners came in slight road cuts.

7-11-1985 Olmsted County Surveyor took reference points before road grading. Drove 5/8" rod under fence running east (fence line approx. 4' north of corner).

8-7-1989 Olmsted county highway department set 5/8" brass plug in centerline of CR 5. RPs-county highway department disc in power pole SW 60.94', county highway department disc in NW corner old school house SW 86.5', county highway department disc in CP east 44.55', county highway department disc in SW corner old school house SE 85.42'.

12-8-2004 Olmsted County Surveyor found 5/8" brass plug in good condition.

10-23-2006 Olmsted County Surveyor found 5/8" brass plug at surface in good condition.

1-27-2010 Olmsted County Surveyor found brass plug at surface in good condition.