Certificate of Location of Government Corner

ID#: 750805 **Description:** SEC COR 7 8 17 18 75 **Date Set:** 8/20/2003 **County:** Olmsted

Section: 08 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of corner post to fences south and west and 23' S of centerline of Maple Trail
Center 14" Green Ash N 20.0'
Center 24" Ash NW 26.5'
Center 28" Oak W 29.0'
Center 36" Oak E 6.5'
Post w/sign 2' South
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes Micheal Karrick set post for corner to sections 7-8-17 and 18. W. Oak 20" S 52° W 180 lks. W. Oak 18" N 33° W 681 lks. Sugar 15" N 43° E 43 lks. Blk Oak 24" S 45° E 78 lks. Random line East between 8-17 12.80 embarrass river runs NE.

Note: No records but B trees in place and iron pipe at corner post for many years used in woodlot and other surveys.

1933 J. Kerr found square oak stake.

11-1938 J. Kerr (S.7 B.14 P.13) found SE 7 ran line West. Also at one time ran line N. Meas North 2698.56 details of this line B.32 P.41 with irons found and other details.

1964 J. Kerr found corner.

1976 County Surveyor found pipe and took additional references.

8-20-2003 County Surveyor found small pipe up 1.0' in good condition. Took local ties and removed pipe. Set CIC on a 5.0' telspar pipe up 0.3'. Took new reference ties.