Certificate of Location of Government Corner

ID#: 750909 **Description:** SEC CEN 9 75 **Date Set:** 5/3/1973 **County:** Olmsted

Section: 09 **Township:** 107N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1 1/4" pipe

Reference Ties:

The corner falls 13' WSW of centerline of CR 103 on curve and 15' south of centerline of residential driveway west
4" telephone box on side to TP E 50.08'
Punchhole in S end 12" CMP WNW 12.89'
Spud on NE side PP NNW 70.46'
This corner is located by GPS measurement

Corner History:

4-7-1870 R. Perry (Book A, Page 105 No. 144) shows center

11-23-1877 Thomas Hunter (Pg.326 No.320), County Surveyor found pole standing by the side of the remains of old stake.

6-5-1900 R. Fraser (Book A, Page 684, No. 608) found stake but did not use

11-23-1960 John Kerr (Bk.80 Pg.57), County Surveyor set CIM as corner by intersecting lines.

1967 J. Kerr set rod at 1/16 corner east and 1/2" pipe as 1/64 corner south.

5-3-1973 County Surveyor after finding true 1/4 corner 8-9 which would move center north, dug entire area to clay, but couldn't find anything. Set 1 1/4" pipe 1.28' north of John Kerr's CIM location. Removed CIM.

9-27-1976 McGhie & Betts found and used pipe.

6-2-1988 R. Brand found and used pipe at center of section.

4-20-1990 V. Fangman found and used pipe.

5-5-1993 V. Fangman found and used pipe.

6-20-1995 V. Fangman found and used pipe. He notes that the pipe is not on the E-W quarter line and has been accepted and used by other surveyors in the section.

10-7-2004 V. Fangman used computed center at intersecting quarter lines.

5-20-2005 County Surveyor found 1 1/4" pipe down 1' with spike in center in good condition.

9-23-2005 V. Fangman set 1/2" pipe with cap at intersection of quarter lines

12-12-2005 V. Fangman found and used pipe.

3-15-2006 V. Fangman used computed intersection of quarter lines.

1-30-2006 County survey crew found 1 1/4" pipe with spike in center down 1' in good condition.

2-16-2008 McGhie & Betts found and used 1 1/4" pipe as center of section 9.

2-21-2013 County survey crew found 1/2" pipe with cap RLS 14888 and 1.6' easterly of that found the 1 1/4" pipe.