Certificate of Location of Government Corner

ID#: 751706 **Description:** 1/4 SEC COR 17 18 75 **Date Set:** 3/9/77 **County:** Olmsted

Section: 17 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2 1/2' east of old N-S fence
Spike & County Survey Disk in W side blazed 12" Box Elder NNW 7.75'
Spike & County Survey Disk in E side blazed 11" Box Elder SSW 7.35'
Post w/sign 2' west
This corner is located by GPS reference stations "Eustice C & D"

Corner History:

5-1854 Gov't Notes: Michael Karrick, Deputy Surveyor; North between sections 17 & 18.
40.00 chs set quarter section post in mound with trench, pits, and charred stake and planted Osage Orange seeds NE & SW.

1-1893 William Fraser, County Surveyor, (Pg.503 No.473) found a stake at the 1/16 West set by Thomas Fraser in an unrecorded survey done in 1890.

1936 county highway department (Bk.84,Pg.74) set a hub midway and on line.

7-1970 County Surveyor measured North from the SE corner section 18 and dug 8'x20' on the west side of the tree row and fence line.

11-18-1970 County Surveyor continued measuring North to the NE corner section 18. The total line came on the east side of the fence so dug again, but found nothing. Set a 3/8"x3 1/2' rod midway and on line between the sections.

4-19-1971 County Surveyor dug again SW of the rod set in 1970, but found nothing.

3-9-1977 County Surveyor set a CIC on a square pipe driven over the 3/8" rod set in 1970.

4-16-1986 County Surveyor found monument top flush with ground surface.

12-9-2004 County Surveyor found cast iron cap on telspar pipe at surface in good condition.