Certificate of Location of Government Corner

ID#: 751806 **Description:** W 1/4 SEC COR 18 75 **Date Set:** 7/11/2005 **County:** Olmsted

Section: 18 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1/2' west of N-S fence
County Survey Disk in N side 24" Boxelder ENE 9.47'
County Survey Disk in E side 24" Elm N 10.54'
Post w/sign 1/2' east
This corner is located by GPS reference stations "Harris A & B"

Corner History:

1854 Gov't Notes Karrick West 1/4 18 Kalmar 107-15. 40.00 set quarter section post level. Elm 24 West 21 links. Elm 12 S 40° East 13 links.

12-10-1900 W. Fraser Pg.702 No.617 found stone set by Dodge County Surveyor.

4-14-1970 Olmsted County Surveyor found 4"x6" topped limestone at least 16" long. Set 8" boulder on top of limestone with shaft of ratchet. Car jack east of stone.

12-14-2004 Olmsted County Surveyor could not find stone.

7-11-2005 Olmsted County Surveyor found 8" boulder with car jack on east side at surface. Tied out boulder and removed. Dug down 1.0' and found limestone tied out and removed. Set 5' cast iron cap on telspar pipe up 0.4' at limestone location.

1-26-2010 Olmsted County Surveyor found CIC up 0.4' in good condition.