Certificate of Location of Government Corner

ID#: 752009 **Description:** SEC CEN 20 75 **Date Set:** 3/11/1981 **County:** Olmsted

Section: 20 **Township:** 107N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

1" square pipe w/cap RLS #8952

Reference Ties:

The corner falls near creek on bottom of slope
Punched + in end of large u-bolt that holds the RCP together NW 15.89'
1/2" rod east and on line to RR spike driven in W side large Box Elder 162.67' east of corner
12" Pine Oak SE 1.3'
Sign in tree 1 1/2' SE
The monument is down 0.2'
This corner is located by GPS reference stations "McClaflin A & B"

Corner History:

5-29-1874 T. Hunter, County Surveyor, (Book A, Page 253, Survey No. 253 and Field Book 3, Page 101), "Found stone near corner of fence, set by R. Perry, Surveyor, as Center of Section."

4-1-1911 C. Larson, County Surveyor, (Book B, Page 152), found a 4"x16"x20" limestone at the center 20.

9-23-1936 County Highway Department, (CHD Book 84, Pages 4 & 73), found stone used in road layout.

9-25-1964 J. Kerr, County Surveyor, found stone and set a Cast Iron Monument (up 6") on top.

3-20-1979 Zenk Engineering found and used Cast Iron Monument.

3-24-1980 McGhie & Betts found and used Cast Iron Monument.

5-19-1980 County Surveyor used Cast Iron Monument for Highway Right of Way Plat No. 17. Took references prior to road construction.

6-2-1980 County Surveyor removed Cast Iron Monument before road grading.

3-11-1981 County Surveyor set 1" square by 35" pipe with cap as the corner at referenced location after road construction.

5-6-1983 V. Fangman found and used 1" square pipe w/cap.

8-8-2001 Brand & Massey Surveying found and used monument.

1-24-2002 Yaggy Colby Associates used 1" square pipe w/cap.

10-24-2002 V. Fangman found and used 1" square pipe w/cap.

4-1-2003 McGhie & Betts used 1" square pipe w/cap.

12-15-2004 County Survey Crew found 1" square pipe w/cap down 0.2' in good condition.

10-17-2007 V. Fangman found and used monument for survey in SW 1/4 sec. 20.

10-22-2007 County Survey Crew found 1" square pipe w/cap down 0.2' in good condition.

2-14-2011 V. Fangman found and used 1" square pipe w/cap.

12-17-2012 V. Fangman found and used 1" square pipe w/cap.