Certificate of Location of Government Corner

ID#: 752104 **Description:** 1/4 SEC COR 21 28 75 **Date Set:** 3/16/2009 **County:** Olmsted

Section: 21 **Township:** 107N **Range:** 15W **Monument Description:** 1" copper plug w/punch mark RLS #15809

Reference Ties:

This corner falls in SE side manhole structure in median of 10th Ave NE
This corner is located by GPS reference stations "Somersby A & B"

Corner History:

1854 Gov't Notes: Karrick, Deputy Surveyor: West on true line between 21 & 28 40.00 chs set quarter section post in mound with trench,pits, charred stake, and planted osage orange seeds NE and SW. 80.00 to section corner.

5-1872 Thomas Hunter (Pg.197 No.207), County Surveyor, states corner gone and no evidence or knowledge. Set 3"x8"x15" stone midway and on line.

6-1876 T. Hunter (Pg.296 No.291) found stone Pg.197.

8-14-1970 County Surveyor dug with tractor and found stone 2.8' deep. Set 1/2" rod on west side of stone and 5/8" rod on east side end of barbed wire dropped over stone. Set CIM and glass over stone.

5-20-2002 County Surveyor found CIM down 0.8' in good condition.

1-24-2006 County Surveyor visited area of corner. Found nothing. Corner destroyed by street construction.

3-16-2009 County Surveyor set 1" copper plug w/punch mark along edge of manhole. The monument falls off the ring in the concrete on the SE side of the structure down 0.4' below top of ring.