Certificate of Location of Government Corner

ID#: 752109 **Description:** SEC CEN 21 75 **Date Set:** 6/10/1976 **County:** Olmsted

Section: 21 **Township:** 107N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1 3/4" pipe

Reference Ties:

The monument is down 1.8'
The corner lines with fences far north and west
This corner is located by GPS reference stations "S & J Fenske A & B"

Corner History:

5-6-1872 Thomas Hunter (Pg.197 No.207) County Surveyor set a 3"x4"x24" stone at intersecting lines.

6-5-1876 T. Hunter (Pg.296 No.291) found stone Pg.197

8-26-1965 John Kerr, County Surveyor found possible corner stone lying flat SE of the corner post and accepted this as the corner location. Set CIM as the corner.

6-8-1976 County Surveyor dug for the recorded stone, but didn't find anything.

CORRECTION OF CORNER: The correct corner is .45' east and 1.32' south of Kerr's CIM (removed)

6-10-1976 County Surveyor reset the corner with a 1 3/4" O.D.x3' pipe down 1' at intersecting 1/4 lines by electronic traverse computation .45' east and 1.32' south of Kerr's CIM (removed). Set electric fence post along side the pipe.

2-21-2006 County Surveyor visited area of corner. Found nothing.

2-3-2012 County survey crew found 1 3/4" pipe in good condition in cultivated field