Certificate of Location of Government Corner

ID#: 752305 **Description:** SEC COR 22 23 26 27 75 **Date Set:** 2/6/2012 **County:** Olmsted

Section: 23 **Township:** 107N **Range:** 15W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The monument is up 0.4'
Post w/sign 0.5' south in E-W fence line
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes Karrick 80.00 set post for corner to section 22-23-26-27 erected mound with trench, pitts, charred stake and Osage Orange seeds at each angle.

5-1872 T. Hunter (P.204 No.212) found stake driven even with surface at inters of fences averred preserved by John Duffin. 1/16 east set stake 19.83-1/2 1309.11.

5-1885 T. Hunter (P.396 No.386) found stake by side of corenr post P.212.

6-1901 R. Fraser (P.699 No.618) found stake running to a point averred by Mr. Johnson owner of lands on North side.

11-27-1973 County Surveyor set 1 1/4" x 30" pipe at this corner.

6-12-1986 County Surveyor dug from 1/2' S of pipe used as cor to S 4-1/2 from pipe and 2' east and west of pipe, found bottom of C.P. to be 1.4 south of pipe digging in of the post disturbed the spot 2' S of pipe E nothing further. Dug 2-1/2 to clean yellow clay. Corner post used in surveys for alignment and sub-division of big plots.

8-4-1993 County Surveyor found 1-1/4" pipe used in other surveys we bent in the pipe top and put an aluminum cap in pipe w/post and sign .5' South.

6-27-2002 County Surveyor found pipe w/cap at surface in good condition.

2-16-2012 County survey crew found 1-1/4" pipe with top compressed to an oval shape. Removed and replaced with a 4' telspar pipe with cast iron cap.