Certificate of Location of Government Corner

ID#: 752306 **Description:** 1/4 SEC COR 22 23 75 **Date Set:** 8/13/93 **County:** Olmsted

Section: 23 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4 1/2' north of centerline of E-W twp road and 6 1/2' east of fence north
County Survey Disk in brace post N 39.15'
This corner is located by GPS measurement

Corner History:

Gov't Notes 40.00 set quarter section post in mound with trench, pitts, charred stake and Osage Orange seeds NE & SW.

1969 McGhie & Betts set 5/8" rod.

8-10-1993 County Surveyor found and pulled McGhie and Betts 5/8" x 11" iron set M&L. Dug with backhoe found 1/2" x 18" iron at surface of old road down 3' from current road top. Found nothing else.

8-13-1993 County Surveyor set cast iron cap on telspar pipe at location of McGhie & Betts M&L 5/8" iron. The corner is 4-1/2' North of centerline 34th St NW and 6-1/2' east of main fence line north. RP's CSD in brace post north 39.15'

2-11-2004 County Surveyor found telspar pipe w/CIC in good condition down 1'