Location of Center of Section

ID#: 752509 **Description:** SEC CEN 25 75 **Date Set:** 5/27/1994 **County:** Olmsted

Section: 25 **Township:** 107N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

1/2" pipe w/cap RLS #14888

County Surveyor recommends using the computed intersection of quarter lines for the center of section.

Reference Ties:

The corner falls in centerline of CR 156, 5-1/2' west of fence south, 9' west of centerline of field entrance north and 12' west of centerline of field entrance south
The monument is at the surface
This corner is located by GPS measurement

Corner History:

4-8-1863 P.C. Compton, County Surveyor, per W.S. Booth, Deputy County Surveyor, (Book A, Page 72, Survey No. 103) set post at intersecting quarter lines. 1/16th East set post midway and online.

5-27-1994 Vince Fangman set 1/2" pipe w/cap #14888 at intersecting quarter lines.

1-30-2006 County Survey Crew found 1/2" pipe w/cap at surface in good condition and measured its position using GPS. The corner falls in centerline of CR 156, 5-1/2' west of fence south, 9' west of centerline of field entrance north and 12' west of centerline of field entrance south.

3-13-2012 Joel Thoreson, County Surveyor, recommends using the computed intersection of quarter lines for the center of section. Based on the county's section breakdown, the 1/2" pipe w/cap, as located by GPS in 2006, falls 0.01' south and 0.05' east of the computed center.

4-6-2012 Fangman Land Surveying found and used 1/2" pipe at intersecting quarter lines.

12-12-2018 Massey Land Surveying found and used 1/2" pipe at intersecting quarter lines.

1-19-2023 WSE Massey Engineering & Land Surveying found and used 1/2" pipe at intersecting quarter lines.