Certificate of Location of Government Corner

ID#: 752704 **Description:** 1/4 SEC COR 27 34 75 **Date Set:** 9/5/01 **County:** Olmsted

Section: 27 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' east of centerline of CSAH 3, 1' south of centerline of CR 134 west and in centerline of twp road east
Disc in PP #22396 SW 67.55'
County Survey Disk in PP #22397 NW 84.98'
Punch mark in top of clamp lug on N end CMP NE 40.2'
Punch mark in top of clamp lug on S end CMP SE 39.7'
County Survey Disk in PP #53480 SE 70.70'
Ref pipe SE 79.85'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Karrick, 40.00 set temp 1/4 sec post west on true line between sections 40.00 set 1/4 sec post in mound 27 & 34 with trench, pitts, charred stake and Osage Orange seeds NE & SW.

1-1870 R. Perry Pg. 128 No. 160, found stone.

8-1927 county highway department found stone, wood stake.

5-25-1970 County Surveyor dug 2' x 3' hole in blacktop 4' deep covering area of point set by Sankstone to within probing of county assumed corner. Later found county highway department had dug for corner extensively in 1964 road in cut slightly old road 2' down. Set CIM flush with road over 3/4" x 26" pipe and glass etc at point set by Sankstone duplicating original 1870 survey procedure.

8-30-2001 County Surveyor set pk nail at surface from 2001 overlay tie out.

6-4-2001 County Surveyor set 1" square pipe w/cap as ref pipe for 2001 overlays. Tied out corner and removed CIM.

9-5-2001 County Surveyor set 1" square pipe w/cap at surface.

8-14-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-5-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.