Certificate of Location of Government Corner

ID#: 753106 **Description:** W 1/4 SEC COR 31 75 **Date Set:** 10/18/2006 **County:** Olmsted

Section: 31 **Township:** 107N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of N-S twp road and 3' north of centerline of Dodge CR 34 west
County Survey Disk in PP SSE 108.25'
Mag nail in PP #40 NE 57.12'
Punch cross in S end 18" CMP NNW 100.07'
This corner is located by GPS reference stations "VMH A & B"

Corner History:

1854 Gov't Notes: Karrick, 40.0 set post and drove 5" charred stake for quarter section post. Built mound, planted osage orange SE and apple seeds NE.

5-1863 Compton Pf.71 No.101; set stone or used corner to set center 31.

5-1871 R. Perry Pg.162 No.185; found part of old stake with old faint pits near. Run west section line, mile short 6 links. Corner found 5 3/4 links east of direct line and 10 links south of midway. Set stone 8x10x23 in place of stake.

6-1873 R. Perry Pg.168; Checked this by avers of Mr.CB? Who claims his fence was run from origianl corner, also Mr. Lehmans for his fence west found first post set which proved stone still correct.

8-18-1970 County Surveyor after measure of 1968 verified by state elctronic and elaborate and detailed measure & line in 1970 set lead slug as corner.

3-11-1980 County Surveyor found lead slug in pavement (set 1970) under blacktop patch and checked 1970 RP's correct.

5-21-2002 County Surveyor found lead slug down 0.6' in good condition. Removed lead slug and set 1" square pipe w/cap at surface.

6-2004 WHKS crew found monument in good condition with ties all in place as described.

1-31-2006 County Surveyor visited area of corner and found corner destroyed due to road construction.

10-18-2006 County Surveyor set 1" square pipe w/cap at surface from computed coordinates. Did not check tie in culvert, all other ties updated.