Certificate of Location of Government Corner

ID#: 813304 **Description:** S 1/4 SEC COR 33 81 **Date Set:** 11/29/1979 **County:** Wabasha

Section: 33 **Township:** 108N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2 1/2' NNW of CP to fences N-S-E
The monument is at the surface
Sign on CP 2 1/2' SSE
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes John Ball, Deputy Surveyor West between sections 4 and 33. 40.00 chs. Set post for quarter section corner. Black Oak 8 N861/2ºE 387 lks. Black Oak 10 N4ºW 266 lks.

12-1891 Thomas Fraser, County Surveyor, (Book A, Page 467, No. 449) states that this corner was gone and obliterated.

11-20-1979 Olmsted County Surveyor dug at the corner of fences N-S-E. Found a 6" square mark in clay which we scraped down 1/2' and then found a 21/2" square mark running down another 1/2' + and tapering to a point. We drove a 1" square by 35" pipe in the mark. The point is 1' NW of an old post standing 21/2' NNW of the present corner post.

11-29-1979 Olmsted County Surveyor set a Cast Iron Cap on a square pipe driven over the pipe set 11-20-1979.

12-21-2009 Olmsted County Survey Crew found cast iron cap on telspar pipe up 0.3' in good condition.

3-2-2010 Olmsted County Survey Crew found CIC/p2 at surface in good condition.