# Certificate of Location of Government Corner

**ID#:** 813305 **Description:** S SEC COR 32 33 81 **Date Set:** 8/14/1980 **County:** Wabasha

**Section:** 33 **Township:** 108N **Range:** 11W **Monument Description:** Cast Iron Monument

**Reference Ties:**

The corner falls 2 1/2' south of centerline of twp road west and in line with fences north and east
County Survey Disk in SE side PP #33081 ENE 54.57'
County Survey Disk in W side stub TP N 59.18'
County Survey Disk in S side gate post E 40.72'

**Corner History:**

9-1853 Gov't Notes: Set post for corner and dug trench. BT's: Burr Oak 14" S 9-1/2°W 177 links. Burr Oak 12" S 4-1/2°E 282 links.

11-14-1979 Olmsted County Surveyor dug here with the backhoe centered on a point 112' west of DNR #10 (and in line with fences north and east and the center of the road west) north 5', south 11', east 5', and west 4' as follows. We found the mark from one large post 1'+ in diameter with rusty nails and pieces of wire. This mark 2' deep, 2-1/2' east of the fence north, and 3' north of the fence east. RP's: CSD west side telephone pole NNW 56.5. CSD south side power pole NE 50.6 3' west and 1' south of this mark we found a deep mark filled with cables we believe to be where a pole stood. We also found a 4-1/2" diameter post 22" long, 6' south of the fence east and 1' west of fence north. RP's to 4-1/2" diam put: CSD west side telephone pole N 65.7. CSD south side power pole NE 57.3. We found nothing further.

8-14-1980 Olmsted County Surveyor set CIM over 1/2" x 19" rod midway and on line between the N 1/4 cor 5 and the N 1/4 cor 4. The corner is in line with the main line of the fence east and in line with the centerline of the road west and in line with the fence north and 9' south of the centerline of road on curve into yard. Pulled 1/2" x 25" pipe found .23 N and .32 east and resently set. RP's: CSD in PP #33081 ENE 54.57. CSD in telephone pole north 59.18.

4-20-1989 DNR found CIM down 0.6'. CSD in PP up 1.3' SE side N 65°E 54.56'. CSD in T.P. up 2.0' west side now cut off N 59.21'. CSD in gate post up 0.8' south side E 40.72'.

10-15-2008 Olmsted County Surveyor found CIM down 0.8' in good condition.