Certificate of Location of Government Corner

ID#: 820607 **Description:** NW SEC COR 6 82 **Date Set:** 8/8/2007 **County:** Wabasha

Section: 06 **Township:** 108N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is at the surface
The corner falls 1' north of centerline of CSAH 11 and 2' east of centerline of twp road south
Center of most southerly and easterly Pine (8") in East row of Pines NNE 132.08'
Nail in PP #32412 NE 61.18'
Punch hole in E end 18" CMP SSE 125.23'
Punch hole in W end 18" CMP SSW 122.04'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes John Ball, Deputy Surveyor 77.33 chs. Intersected 2nd Standard Parallel 615 links East of the quarter section corner to the South boundary of Section 36, Twp. 109N, Range 13W. Set post and drove charred stake corner to Ranges 12 and 13 West of Twp. 108 North.

1875 State Law required township monuments to be placed at the township corners.

5-11-1976 Olmsted County Surveyor dug with the backhoe and found a 10"x10"x36" cut stone township monument 4' deep in black soil beneath the oldest road. Also found a 4"x4"x12" stone .8' East and pieces of wood running down 1-1/2' 1.4' South and 1.4' East of the cut stone monument. Set a piece of steel post beside and cut stone monument and a 3/8"x20" pipe over it and at the road surface. This road is to be graded.

9-20-1979 Olmsted County Surveyor set a 10" C.I.M. over a 2' piece of telspar from references in 1976.

4-1991 Olmsted County Surveyor in state wide aerial targeting project found CIM in good condition in E-W blacktop road.

3-12-2007 Olmsted County survey crew found CIM down 0.3' in good condition.

7-3-2007 Olmsted County survey crew found CIM down 0.3' in good conditions. Removed CIM and found telspar pipe down 1.2' in good condition and removed for 2007 overlays.

8-8-2007 Olmsted County survey crew set 1" square pipe w/cap at surface from 2007 overlay tie-out. Updated ties.

12-2-2011 County survey crew found 1" square pipe with cap in good condition.