Certificate of Location of Government Corner

ID#: 830106 **Description:** 1/4 SEC COR 1 2 83 **Date Set:** 7/9/2012 **County:** Olmsted

Section: 01 **Township:** 108N **Range:** 13W **Monument Description:** 1" Square Pipe with Cap "42638"

Reference Ties:

The monument is down 0.1'
The corner falls 0.2' west of centerline CSAH 11 and in line with fence east
This corner is located by GPS reference stations "Walker A & B"

Corner History:

1854 William Yerby; 40.0 made mound of earth & sod deposited charcoal and made trench, pits, and planted osage orange seed S&W. 77.67 intersect 2nd correction line 6.62 links east of grade post.

8-28-1985 V. Fangman set pk nail at surface in centerline of CSAH 11 and in line with fence east.

8-3-1993 County Surveyor found V. Fangman PK nail in good condition. Referenced the location in preparation for road resurfacing.

7-8-1994 County Surveyor found and checked pk nail which had been reset by the County Highway Department using reference ties after the road resurfacing.

3-20-2007 County survey crew found pk nail at surface in good condition and located by using GPS reference stations

6-2011 Pk nail destroyed by road resurfacing.

7-9-2012 County survey crew set a 1" square pipe, 2' long with cap "42638" at the previously measured PK nail location.