Certificate of Location of Government Corner

ID#: 830605 **Description:** W SEC COR 6 7 83 **Date Set:** 9/21/90 **County:** Olmsted

Section: 06 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' east of gate post
Post w/sign 1' west
This corner is located by GPS reference stations "Webster A & B"

Corner History:

10-1853 Gov't Notes, John Ball, Deputy Surveyor North between sections 7 and 12 80.00 chs. set post for corner to sections 7, 6, 1, 12 10" bur oak S85°W 224 lks. 12" bur oak N88°W 231 lks. 10" bur oak N20°E 197 lks. North between sections 1 and 6 8.76 chs. 14" bur oak

9-12-1990 County Surveyor, found possible bearing tree at S85°W 146 1/2' to corner post to fences N-E-W

9-21-1990 County Surveyor dug at complex of 3 corner posts, found nothing set telspar pipe with cast iron cap in middle of corner posts which fit 34" bur oak bearing tree S85°W 147.6'. RPs-Monument by corner post to fences E-W-N, Survey marker sign on post west 1.0', Spike and C.S.D. in 20" bur oak west 23.39', Spike and C.S.D. in 20" boxelder SW 35.74'.

10-14-2005 County Surveyor found telspar pipe w/CIC in good condition up 0.7'. Monument falls 1.5' east of gate post. Both trees with ties are down, bearing tree also down.