Certificate of Location of Government Corner

ID#: 830608 **Description:** N 1/4 SEC COR 6 83 **Date Set:** 6/21/2013 **County:** Olmsted

Section: 06 **Township:** 108 **Range:** 13 **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is at the surface.
Post with sign, 2' north.
This corner is located by GPS measurement

Corner History:

7-19-2007 County survey crew visited the area, found no survey monuments

5-16-2013 Joel Thoreson, Olmsted County Surveyor, visited the area of the corner. Found a wood fence post in line with field division East-West and also found the remains of an old fence and field division south which are in line with the wood post. Accepted the wood post and N-S fence as marking the N-S quarter line of Section 6.

6-21-2013 Olmsted County survey crew set a 4' telspar pipe with cast iron cap on line between the southwest corner of Section 31-109-13 and the south quarter corner of Section 31-109-13 and in line with old fence south. The corner is 3' south of wooden fence post.