Certificate of Location of Government Corner

ID#: 831305 **Description:** SEC COR 13 14 23 24 83 **Date Set:** 8/1/1983 **County:** Olmsted

Section: 13 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 1.4'
The corner falls 5' east of centerline of N-S twp road and 1' south of fences east and west
Punch hole in top W end CMP SW 39.91'
Punch hole in top E end CMP SE 33.96'
This corner is located by GPS measurement.

Corner History:

9-1854 Gov't Notes William Yerby, Deputy Surveyor North between sections 23 and 24. 80.00 chs. Set section corner post in mound. Corner to sections 13, 14, 23 & 24. Deposited charcoal. Made trench and pits. Planted Osage Orange seed N.W. & S.E.

11-1877 Thomas Hunter, County Surveyor, (Book A, Page 323, No. 317, and Old Fieldbook 5, Page 26) "This corner comes in the center of road and it has been filled in several feet high above the corner but Mr. C. Schacht avers that he set the corner post on the west side of the road exactly on line with the original corner when standing in mound before the road was worked or filled in and exactly 33 feet from said corner. We therefore fixed said point as the corner. Measured south 39.97 chs. to old fence line running west at 1/4 Cor. 23-24 (used as N-S location for 1/4 Cor. 23-24.).

8-1-1983 County Surveyor: This corner is in deep fill in N-S road (8' deep to clay line). Dug for corner in line with fences East and West from 5' West of road centerline to 8 1/2' East of centerline. In an old road 3' deep we found where someone had dug from there down for 3' to the top of a hard layer of black dirt stopped (still 2' to clay). This road is probably the road referred to by Hunter and diggings may be his. They had set a 3-1/2" x 4-1/2" x 11" limestone (top down 4-1/2' from present road) with a horse shoe along side in their diggings as a corner. Removed stone and dug to clay but found nothing farther. Stone 1' South of fence line East and West and 5' East of the centerline of the N-S road.

8-3-1983 County Surveyor accepted the stone location for this corner and set a 6' long telspar pipe with a cast iron cap. Accepted corner here since it lines well with fence line East and West as called for by Hunter and also agrees with Hunter's measure to 1/4 Cor. 23-24 (we measure 2635.66') as set this survey (see Certificate filed). The corner is also just 2.85' East of the prorated Gov't location between 1/4 Cor. 14-23 and 1/4 Cor. 13-24.

9-7-2010 County survey crew found CIC in good condition