Certificate of Location of Government Corner

ID#: 831405 **Description:** SEC COR 14 15 22 23 83 **Date Set:** 7/8/1994 **County:** Olmsted

Section: 14 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 11 and 3' south of fence west
The monument is down 0.8'
County Survey Disk in N side CP WNW 50.81'
County highway disk in TP E SE 50.75'
County highway disk in PP SE 76.42'
County highway disk in PP #35193 SE 76.51'
Ref pipe SE 44.24'
This corner is located by GPS measurement

Corner History:

1944 County Engineer found the common corner Secs. 14,15, 22, 23, Farmington Township which was evidenced by boulder monument. Placed 1" drill rod.

6-14-1983 County Surveyor found drill rod down 3" in centerline N-S C.R. #11 and 2 1/2' South of fence line West. Rp CSD in N. side corner post WNW 50.81'

6-22-1993 County Surveyor referenced corner before milling and resurfacing.

7-8-1994 County Surveyor set 1" square pipe w/cap as corner in centerline CR #11 & 3' south of fence line west. Rp's old county highway department disk in PP #35193 SE 76.51'

10-10-2002 County Surveyor found 1" square pipe w/cap in good condition down 0.1'.

5-24-2011 County survey crew found 1" sq. pipe with cap in good condition. Drove pipe down below bituminous in preparation for road surface milling and overlay.