# Certificate of Location of Government Corner

**ID#:** 831805 **Description:** W SEC COR 18 19 83 **Date Set:** 10/11/2005 **County:** Olmsted

**Section:** 18 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 1' NW of CP to fences N-S-E-W
Post w/sign 2' north
This corner is located by GPS measurement

**Corner History:**

1853 Gov't Notes John Ball, Deputy Surveyor
North between sections 19 and 24. 80.00 chs. Set post and drove charred stake for corner to Sections 13, 18, 19 and 24. Built mound with trench as per instructions. Planted S.E. Osage orange and N.E. apple seed.

5-1877 Thomas Hunter (P. 308 No. 302), County Surveyor, found fence post in mound and pits plain. Set W. 1/4 Cor. Sec. 19 midway and on line.

6-1878 T. Hunter (P. 327 No. 321) found post in mound.

6-1879 T. Hunter (P. 361 No. 352) found cedar post in mound.

5-18-1976 County Surveyor dug 3'x3' on N.W. side of corner post to cover doubling line and measure of stone found at W. 1/4 Cor. 19. Found nothing. Accepted corner post as corner as per Hunter's Survey #302. Set C.I.M. over 1/2"x3' pipe 1' N.W. of the corner post.

10-11-2005 County Surveyor found CIM leaning down 0.3', removed CIM and found 1/2' pipe down 2 1/2'. Set 7' telspar pipe w/CIC over pipe up 0.3'. Set sign and post 2.0' north.