Certificate of Location of Government Corner

ID#: 831809 **Description:** SEC CEN 18 83 **Date Set:** 5/19/1976 **County:** Olmsted

Section: 18 **Township:** 108N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
Stone with 1 1/4" pipe on west side

Reference Ties:

The monument is down 2.5'
The corner falls 1 1/2' west of N-S fence and 4' WSW of corner post
This corner is located by GPS measurement

Corner History:

6-3-1879 T. Hunter P.361 No.352 and others set stone at true inters lines from 1/4 corners. 16 south set stone M&L 19.97-3/4, also staked line east of above 1/16 for fencing.

5-19-1976 County Surveyor at 1/16 south found 5"x5"x10" pointed boulder 1' deep with base in clay and base of old post on SW side. Stone 1' S of fence E and 2' W of corner post. Set 11" long square iron on N side and RR spike on S side.

5-19-1976 County Surveyor found 3"x6/10"x11" limestone 2-1/2' deep on W side of old corner post but well below base of post. Packed stone in small boulders and put 1-1/4"x12" pipe on W side. Stone now 1-1/2' W fence lines N and S and 4.2 WSW new corner post.

9-17-2010 County survey crew found stone in good condition