Certificate of Location of Government Corner

ID#: 832604 **Description:** 1/4 SEC COR 26 35 83 **Date Set:** 8/3/1983 **County:** Olmsted

Section: 26 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.8'
The corner falls 3' south of centerline of E-W twp road and 4' east of fences north and south
County Survey Disk in CP NNW 45.99'
Punch hole in E end 18" CMP SE 40.11'
Punch hole in W end 18" CMP S 28.00'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes William B. Yerby Deputy Surveyor West on true line between sections 26 and 35. 39.94 chs. Set quarter section post in mound of earth, sod and deposited charcoal. Made trench and pits and planted osage orange seeds north and south. 79.88' To section corner

10-1946 John Kerr County Surveyor (Kerr Book 32 pages 27, 28, 29) Set 1-1/4" x 4' pipe as 1/4 corner 26-35 midway 2630.35' and on line between stones found at section corners east and west. He used this corner to set the 1/16 corner north , a boulder with a cross, midway 1320.93' and on line to the center of section 26 (a 1-1/4" x 4' pipe) set this survey at intersecting 1/4 lines.

11-20-1963 John Kerr, County Surveyor found 1-1/4" pipe set new 1-1/4" x 20" pipe with C.I.M. over as 1/4 corner 26-35.

6-15-1963 County Surveyor found C.I.M. down 32" in road set 3/4" re-rod riser.

7-20-1983 County Surveyor dug 8.5' north, 4.5' east, and 5' west of 3/4" re-rod 4' deep found a black mark in clean clay, about 8" in diameter with wood pieces, trimmed up appeared 3"x3" square 3.85' north and 2.45' east of 3/4" re-rod.

8-2-1983 County Surveyor dug further north found nothing.

8-3-1983 County Surveyor set C.I.M. over 3/4" x 20" iron at 3"x3" mark found 7-20-83.

9-10-2010 County survey crew found CIM in good condition