# Certificate of Location of Government Corner

**ID#:** 833004 **Description:** 1/4 SEC COR 30 31 83 **Date Set:** 6/20/1980 **County:** Olmsted

**Section:** 30 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls under E-W fence
County Survey Disk in NE side Burr Oak NW 42.98'
County Survey Disk in NW side 22" Burr Oak NE 35.74'
County Survey Disk in N side 24" Burr Oak E 11.52'
Post w/sign 2' south
This corner is located by GPS reference stations "DS & Morris"

**Corner History:**

5-1854 Gov't Notes - William B. Yerby, Deputy Surveyor Course S89º57'E on true line between sections 30 and 31. 38.07 chs. Set a quarter section post in mound of earth and sod. Deposited charcoal. Made trench and pits. Planted Osage orange seed North and South. 78.07 chs. To section corner.

5-12-1863 P.C. Compton, County Surveyor, (Book A, Page 69, No. 98) used the corner to set the 1/16 West at proportionate Gov't measure.

3-25-1879 Thomas Hunter, County Surveyor, (Book A, Page 355, No. 347 and Old Field Book 5, Page 95) "1/4 post missing but Mr. R. Healy pointed out a certain fence post in his old fence which had certain marks on it cut with a knife which he says he set in the original mound and marked so as to distinguish it. Marked the post near the ground 1/4S." He used this corner to set the 1/16 West on line and at proportionate Gov't measure (a temporary stake). He also set a stake at the 1/16 North, a stake 5.00 chs. North of the 1/16 North, a temporary stake at the Center 30, and a stake at the 1/16 North of the Center 30.

5-6-1980 County Surveyor dug at the 1/16 West at Hunter's measure from W. Sec. Cor. 30-31 and under the E-W fence. Did not find anything. Dug at 1/4 Cor. 30-31 at Hunter's measure from W. Sec. Cor. 30-31 and under the E-W fence. Found an 8" square mark running down into clay.

6-19-1980 County Surveyor dug at the 1/16 North but did not find anything. Note: In a 1976 survey we looked for several of Hunter's corners in the interior of Section 30 but did not find anything.

6-20-1980 County Surveyor set a 3' long square pipe with a Cast Iron Cap as the corner at the location of the mark found 5-6-1980.

12-2-1996 County Surveyor found cast iron cap on telspar pipe under E-W fence with 1980 ref. Trees still inplace. Set sign & post 2' south of monument.

12-20-1997 McGhie & Betts Found monument inplace and checked the references.

10-20-2010 Brian Veronen, MNDOT LSIT, found cast iron cap on telspar pipe in good condition and checked ties.