Certificate of Location of Government Corner

ID#: 833404 **Description:** S 1/4 SEC COR 34 83 **Date Set:** 10/2/2012 **County:** Olmsted

Section: 34 **Township:** 108N **Range:** 13W **Monument Description:** 1" Square Pipe with Cap RLS 42638

Reference Ties:

The monument is at the surface.
The corner falls 3' west of centerline of CSAH 11 south and in centerline of CSAH 14
This corner is located by GPS measurement

Corner History:

10-1853 John Ball, 40.00 set post & drove charred stake for qr. Section corner built mound with trench per instructions. Planted SE Osage Orange Seed NE Apple Seed.

5-13-1873 T. Hunter, (Book A, P.223, No.226) found remains old stake in center road by digging. Set marked stake with small stones around bottom. 16 east set stake M&L 20.00. 16 south set stake on line at 20.86' then 19.99' to center.
16 center NE1/4 3 set stake inters lines.

11-13-1877 T. Hunter, (Book A, P.324, No.318) found stake and stones as P.223. 16 east found stake P.223 M&L 20.00. 16 north set temp stake M&L 19.981/4. 16 center SE1/4 34 set stake with boulder on south side inter lines.

10-25-1893 W. Fraser, Book A, P.536 No.498) found stake and stones set by Hunter P.223. Measure west 40.02' to section corner set M&L on town line.

1930 County Highway Department (Book #58 Pg.35) found remains of old stake surrounded by limestones on edge.

?? County Highway Department set 8"x8"x30" concrete monument.

11-1964 J. Kerr found monument set CIM over corner had to break off lower section of CIM. Spud power pole NW 106.2'. Spud tele pole SW 108.2'. Punched cross east end field culvert N24.62.
1/16 east set 7/8" rod flush in blacktop M&L 1318.92. Disc PP N 45.4'. Bolt in E end field culvert NE 42.6'.

7-11-1990 County Surveyor found CIM in good condition. In centerline of E-W road and 4.0' west of centerline of CR# 11 S. RP-spud in pp# 24369 NW 106.08'.

7-30-1993 County Surveyor set 1" square pipe w/cap on line to Radio Tower SW of corner to ref. Pipe w/cap. Used red light on tower as sight. The ref pipe is ± 90' west of centerline CR#11 and ± 70' south of centerline CR#21. VA 90° 35'58". Slope 102.78' Hor 102.78'.

7-8-1994 County Surveyor set 1" square pipe w/cap in CR 14 & 11 Intersection at 1993 referenced location. Spud in PP#24369 NW 106.09'. The corner falls in E-W centerline & 3' west of centerline CR #11 south 1" sq. pipe w/cap SW 102.78'.

10-27-2005 County survey crew found 1" square pipe w/cap broken in half, tried to drill out old cap but pipe was being driven down. Took local ties and removed. Found concrete monument down 1.7', ties matched.

10-28-2005 County survey crew set 1" square pipe w/cap from local ties.

4-3-2006 County survey crew found 1" square pipe w/cap at surface in good condition.

5-23-2011 County survey crew found 1" sq. pipe in good condition. Removed the pipe in preparation for bituminous overlay of CSAH 11.

10-2-2012 County survey crew set 1" square pipe with cap at previously measured GPS location.