Certificate of Location of Government Corner

ID#: 840605 **Description:** W SEC COR 6 7 84 **Date Set:** 3/17/2003 **County:** Olmsted

Section: 06 **Township:** 108N **Range:** 14W **Monument Description:** 5/8" Copper Plug w/punch mark

Reference Ties:

The monument is at the surface.
The corner falls 350' ± east of farm bldgs at end of cattle lane
County Survey Disk in stub PP E 69.27'
Sign in concrete wall/barricade 31 1/2' south
This corner is located by GPS reference stations "Mm Mm Good A & B"

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor North between sections 7 and 12. 80.00 chs. Set post and drove charred stake. Boulder 2' bears N 80° W 11 links.

5-1877 Thomas Hunter (Book A P. 309 No. 303), County Surveyor, "at E (W. 6-7) found mound and pits with old original stake broken off & lying by its side. Also the stone mentioned in U.S. field notes as witness, drove old stake in mound by side of stub of said stake." Set the 1/16th South midway (19.94 1/2 chs.) and on line.

5-1893 William Fraser (Book A P. 533 No. 496), County Surveyor, "at E (W. 6-7) Found stone boulder with mark in center planted in corner. Tested it by the witness boulder and found it to be correct." Measured 38.61 chs. East to 1/4 Cor. 6-7 and 80.85 chs. North (see C.S. about this measure) to the N.W. Cor. 6.

5-1898 William Fraser (Book A P. 629 No. 569), County Surveyor, found the corner stone and witness boulder. Set the 1/16th West midway (19.77 chs.) and on line.

6-1902 C. Armstrong (Book B P. 54) "found stone and witness stone in U.S. notes."

6-1902 C. Armstrong (Book B P. 56) found the corner.

7-1964 John Kerr (certificate filed), County Surveyor, found a 1 1/4" x 18" pipe in pasture. Set a C.I.M. over the pipe. R.P.: Drillmark in large boulder W. 7.2, corner lies 900' ± east of farm bldgs at end of cattle lane.

10-1974 County Surveyor found Kerr's C.I.M. but the witness boulder was gone.

9-28-1977 Mn/Dot found the C.I.M. and took references.

10-1977 County Surveyor found Kerr's C.I.M. during an extensive survey in this area. Measured 2606.99 West to 1/4 Cor. 1-12, 2542.67 East to 1/4 Cor. 6-7, 2630.07 South to W. 1/4 Cor. 7, and 5327.39 North to the N.W. Cor. 6.

1-30-2003 County Surveyor did not find CIM, presumed destroyed by elk farm development.

3-17-2003 County Surveyor set 5/8" copper plug w/punchmark at surface in elk farm compound at computed location from GPS data. Set survey marker sign in concrete wall/barricade 31.5' South and CSD in stub power pole (no #) 69.27' East.

3-1-2010 Rudy Martin, MN/DOT Crew Chief, found 5/8" copper plug with punchmark in good condition.

9-1-2011 County survey crew found 5/8" copper plug with punchmark in good condition.