Certificate of Location of Government Corner

ID#: 840606 **Description:** W 1/4 SEC COR 6 84 **Date Set:** 4/28/2003 **County:** Olmsted

Section: 06 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface
The monument is in a cultivated field.
County Survey Disk in 3 prong tree surrounded by boulders NW 166.8'
Post 2' east
This corner is located by GPS reference stations "Badger A & B"

Corner History:

5-1877 T. Hunter Pg.809 No.303; Found old stake remains. Set new stake in its place.

9-1893 W.Fraser Pg.533 No.496; Found stone and stake in fall 1892 and now gone. Set stone at 1/16 north at point set in 1892.

6-1894 W.Fraser Pg.550 No.508; Corner gone. Replaced as before by prop. Gov't meas. Set boulder stone and stake.

6-1902 C.Armstrong Pg.54 B S1; Corner gone. Set boulder 8x8x16 2' deep on line between 1/16 corner north and SE corner S1. 16 south set bould, 16 north found boulder.

6-1902 C.Armstrong Pg.56 B S6; found corner, 2' deep boulder. 16 north found corner, 16 south found corner, 16 center NW 1/4 6 set iron 1 1/2x22. 16 center SW 1/4 6 found stake,set limestone.

5-1975 County Surveyor set a 7x7x14 boulder with small pieces of lath over spot in clay until checked.

10-1-2002 County Surveyor did not locate boulder.

4-28-2003 County Surveyor set 5' telspar pipe w/cast iron cap in Hoehne's Brothers Elk pasture from computed location from GPS data down 0.1'. CSD w/concrete nail in SW side of 3 prong tree surrounded by boulders SE 166.43'. Set sign and post 2.0' East.

4-13-2011 Mike Hendrickson, MNDOT, found cast iron cap at surface. Left monument as found. Measured the following reference ties:
Post with sign - 2' east
County survey disk in 3 prong tree surrounded by rock pile - 166.8' Northwest

9-1-2011 County survey crew found cast iron cap on square telspar pipe in good condition