Certificate of Location of Government Corner

ID#: 841204 **Description:** 1/4 SEC COR 12 13 84 **Date Set:** 3/26/2002 **County:** Olmsted

Section: 12 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe with cap RLS #15809

Reference Ties:

The monument is at the surface.
The corner falls 1' north of centerline of CSAH 12, in centerline of CR 114 north and 3' east of centerline of twp road south
County Survey Disk in PP #2829 SE 52.57'
County highway disk in PP #43746 NW 89.09'
County highway disk in PP #44010 SW 58.83'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, M.Karrick; 40.0 set temp 1/4 section post west on true line between sections 12 & 13. 40.0 set 1/4 section post in mound with trench, pits, charred stake and osage orange seeds NE & SW.

No courthouse records on this corner.

J. Kerr found stone at this corner in early survey, set pipe.

1939 County Highway Department Bk.113 Pg.77; found stake and 2 spikes.

8-1964 J.Kerr set CIM over pipe. RPs- disc in pp SW 56.6, 120D in 30" cottonwood NW 50.35, disc in pp NNE 62.4, NW corner schoolhouse foundation SE 94.25.

7-18-1990 County Surveyor found 60D spike and 2 conc. Nails intersection of CR #12 & CR #114. Found 1/2" twisted rod. Set CIM over iron. RPs- CSD in pp# 2829 SE 52.50, county highway department disc in pp# 43746 NW 89.09, county highway department disc in pp #44010 SW 58.79, corner is in centerline of E-W-N roads and 3' east of centerline of Twp road south.

6-6-2001 County survey crew found CIM at surface in good condition.

6-19-2001 County survey crew set 1" square pipe w/cap as ref pipe for 2001 overlays. Tied out corner and removed CIM.

3-26-2002 County survey crew set 1" square pipe with cap at surface from 2001 overlay tieout.

7-25-2005 County survey crew found 1" square pipe w/cap at surface in good condition.

10-29-2012 County survey crew found 1" square with pipe with cap in good condition.