Certificate of Location of Government Corner

ID#: 841206 **Description:** 1/4 SEC COR 11 12 84 **Date Set:** 11/2/2004 **County:** Olmsted

Section: 12 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls midway down on steep slope West to East and in wooded area
County Survey Disk in 8" tree SW 1.62'
County Survey Disk in 8" Burr Oak ESE 20.58'
Post w/sign 2' north
This corner is located by GPS reference stations "Wayne A & B"

Corner History:

1854 Gov't Notes, M.Karrick; 40.0 set 1/4 section post. RPs- 7" burr oak N89 W173, 8" burr oak N13 E170.

5-1900 C.Armstrong Pg.668 No.594; Found no trace of corner. Set corner40.17 and drove burr oak stake and piled stones around it.

5-1947 John J. Kerr set 1" pipe Book 34 page 14 by midway and on N-S section line. RPs- S 3 3/4°E 23" burr oak 170.6', S44°W 6" burr oak 1.4'.

1969 Tom Ferguson found pipe.

5-7-1970 County Surveyor left pipe as found and piled some local stones around it. Set steel post east of pipe. RPs- hub &20D on west side 12" burr oak in fence south 32.22', J.Kerr b tree now 8" burr oak SW 1.4', corner lies halfway down wooded slope east of field.

9-24-1990 County Surveyor found pipe packed in stones in good condition. B.T. SW is now 8". Set survey sign and post 1' South of pipe. R.P.'s: Spike and CSD in 8" Bur Oak ESE 20.48. Spike and CSD in 8" Bur Oak SW 1.58.

11-1-2004 County Surveyor found 1" pipe with top slightly smashed. Took local ties and removed pipe.

11-2-2004 County Surveyor set 2.6' telspar pipe with cast iron cap up 0.3' from local ties. Set post w/sign.