Certificate of Location of Government Corner

ID#: 841305 **Description:** SEC COR 13 14 23 24 84 **Date Set:** 5/9/2007 **County:** Olmsted

Section: 13 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1/2' south of E-W fence and 53' east of easterly N-S fence
County Survey Disk in S side 18" Box Elder ESE 8.17'
Post w/sign 2' north
This corner is located by GPS reference stations "Coon Dog A & B"

Corner History:

1854 Gov't Notes: Michael Karrick, Deputy Surveyor North between sections 23 and 24. 80.00 chs. Set post for corner to sections 13,14,23, and 24. Burr Oak 10" N53W 295 lks. Bur Oak 7" S22E 370 lks. Dug trench.

1916 Corner post used as corner in Power Dam Survey.

8-1929 John Kerr (Bk. 2), County Surveyor, found red cedar post claimed by adjoining land owners as the accepted section corner.

3-19-1976 County Surveyor set a 1/2" x 15" rod (up 4") as corner on S. side of corner post to fences N-E-W. survey sign to corner post and set steel post south of corner. RPs- CSD east side of pp S30.06, spike & CSD south side 8" box elder ESE 8.40

8-1993 County Surveyor found 5/8" iron set in 1976 in good condition. Nailed survey sign to corner post and set steel post south of corner.

11-2-2004 County Surveyor found 1/2" rod up 0.2' leaning east.

5-9-2007 County Surveyor found 1/2" rod up 0.2' leaning east. Straightened rod, took local ties and removed. Set 4 1/2' telspar pipe w/CIC up 0.2' from ties.