Certificate of Location of Government Corner

ID#: 842106 **Description:** 1/4 SEC COR 20 21 84 **Date Set:** 5/9/2007 **County:** Olmsted

Section: 21 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 51 1/2' south of centerline of CR 112, 2' east of stub fence south and in line with fence north
Northeast corner of house SW 104'
County Survey Disk in N side 36" Willow SW 68.90'
County Survey Disk in E side telephone brace post S 13.07'
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1854 Gov't notes, M. Karrick; 40.0 set 1/4 section post in mound with trench, pits, charred stake, and osage orange seeds NE & SW.

7-1912 C.Larson Pg.196; Set stake

1913 Corner gone. Set corner.

4-1960 J.Kerr Bk.78 Pg.75; Set iron as corner.

6-26-1964 J. Kerr set CIM over iron. Corner comes in open culv. Field south of road. RPs- NE corner house SW 104.1, steel fence corner on N side road RW N 85.55', spike tele pole NW 42.35', approx. centerline AE-W road N 52.0'.

5-1974 Cedric Schutz dug up a large concrete monument in the center of the road 54.56' north of the CIM set by Kerr. Top of concrete down 1.7' in the road. Didn't use this monument as origin unknown.

4-2-2001 County Surveyor found CIM down 1' in good condition.

1-30-2003 Mn/DOT Survey Crew found monument in good condition.

9-22-2004 Mn/DOT Survey Crew found monument in good condition.

5-3-2007 County Surveyor visited area of corner. Found corner destroyed due to TH 52 and CR 112 overpass construction.

5-9-2007 County Surveyor set 5' telspar pipe w/CIC from coordinates. Did not check ties to NE corner of house. CSD w/concrete nail in N side of 36" Willow SW 68.90' & CSD w/concrete nail in E side of telephone brace post S 13.07'.

5-7-2008 V. Fangman found monument in good condition.