Certificate of Location of Government Corner

ID#: 842305 **Description:** SEC COR 22 23 26 27 84 **Date Set:** 4/27/67 **County:** Olmsted

Section: 23 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 3' north of E-W fence and 11' west of random woods fence south
Large cresote treated fence post ESE 27.89'
Drag tooth in 14" Oak SSW 18.52'
Drag tooth in 30" Box Elder WSW 22.68'
8" x 16" concrete block lies just South of monument near surface
Post w/sign 2 1/2' south
This corner is located by GPS reference stations "Goodman A & B"

Corner History:

1854 Gov't notes, M.Karrick; 80.0 set post for corner to section. Erected mound with trench, pits charred stake, and osage orange seeds at each angle.

6-1881 T. Hunter Pg.123 No.371, unrecorded. Section sub divided and shows north line S26 at 39.66 M & L which indicated N 1/4 corner set M & L to set center.

5-1902 W.Fraser Pg.18B; Referred to Hunter's unrecorded survey as pg.123 of field book for J.D.Blake.

1941 J.Kerr Bk.23A, power dam survey; Found very little rotted, but definate stake 1.5' south of old corner post. Drove 1/2"x3' pipe thru stake. Set stones about pipe.

8-27-1941 J.Kerr Bk.25 Pg.70; Meas. North line 26, 4300' by tirangulation. Set point close to east end of line. This line a nightmare.

4-27-1967 County Surveyor found iron, set CIM over pipe. RPs-pepsi cap in new 6" creosote post 3' S of E 27.89, harrow tooth driven 1' up E side 14" oak SSW 18.52, harrow tooth driven up 2' N side 30" elm WSW 22.68, corner 3' N of E-W fence and 11' W of fence running south.

6-23-1981 County Surveyor found C.I.M. inplace. Set survey marker sign & post 2.45' South of C.I.M.. Checked tie measurements.

7-23-2004 County Surveyor found CIM down 0.1' in good condition.