# Certificate of Location of Government Corner

**ID#:** 843605 **Description:** S SEC COR 35 36 84 **Date Set:** 6/11/1993 **County:** Olmsted

**Section:** 36 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls in centerline of CSAH 14 and in centerline of CR 133 south
This corner is located by GPS measurement

**Corner History:**

4-1875 T. Hunter Pg.270 No.268; Found corner post 50 links north of south road fence which Mr. J.Klee avers original corner stood.

1-1900 R. Fraser Pg.649; Found old post mentioned by T. Hunter, but found no remains of corner post.

1938 county highway department Bk.95 Pg.2; Set 3/4"x3' iron pipe. RPs- hub NE 100', spike 18" blazed ash N 69.6

1916 Power dam survey found stake

8-1-1958 J. Kerr found iron pipe.

1965 county highway department Bk.310; set 3/4" rod.

1972 McGhie & Betts; Tied out county highway department 3/4"x3' pipe. RPs- nail & disc in TP NE 46.52', nail & disc in TP NW 36.95, crossed nails in PP SW 63.36', nail & disc in brace post SE 46.48.

4-1979 County Surveyor found 1/2" iron.

6-1980 County Surveyor; found 2"x2" hub over 3/4" pipe set by Kerr in 1938.

3-1985 Vince Fangman found local RPs to pipe found in 1980. Set 3/4" capped pipe as corner. Found PK nail ± 1.3 N and ± .3 west. RPs- crossnail in PP SW 62.18, nail & disc in top sawed off PP NE 47.33, crossnail in TP SE 45.35. Set corner at this location at instruction of County Surveyor.

1991 county highway department took reference to top flashing light on Radio Tower SW. Set 1" square pipe w/cap.

6-11-1993 County Surveyor set 1" square pipe w/cap as corner. The corner falls in centerline CR 14 and in line of centerline CR 133 running south.

5-27-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.

10-9-2009 County Surveyor found 1" square pipe w/cap at surface in good condition.