# Certificate of Location of Government Corner

**ID#:** 850109 **Description:** SEC CEN 1 85 **Date Set:** 2/20/2001 **County:** Olmsted

**Section:** 01 **Township:** 108N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
Iron pipe w/cap RLS #21940

**Reference Ties:**

This corner is located by GPS reference stations "Challenged A & B"

**Corner History:**

6-1902 Ch. Armstrong (P.54B) set boulder stone 10x12x16 at true inters lines. Came 10' west of N-S fences. 16 north set limestone 3x8x20 at 19.94-1/2 1316.2' then 20.41 1347.06' to N 1/4 a stone set. 16 center NE 1/4 set limestone 2x12x24 found an old corner S89°W 9 lks not correctly run in, destroyed old corner. 16 center NW 1/4 set limestone 4x12x14 at inters lines, set witness stone 5' west corner set a 5"x11"x14" granite boulder marked witness corner on each side. 16 west set boulder 4x16x20 with iron stake below M&L 20.08 1325.28'. 16 south found old stone M&L 19.78 1305.48" staked line east for fencing.

2-20-2001 GGG set iron pipe w/cap #21940 at intersecting quarter lines.

4-29-2004 GGG, Inc. used computed center.

2-22-2006 County Survey Crew found 3/4" pipe without cap in good condition. Pipe found is 1.85' north and 3.06' west of intersect.

5-19-2010 County Survey Crew looked for GGG pipe w/cap at intersect and found nothing.