Certificate of Location of Government Corner

ID#: 850308 **Description:** N 1/4 SEC COR 3 85 **Date Set:** 11/25/81 **County:** Olmsted

Section: 03 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 9' west of N-S fence and 16' south of old fence west
County Survey Disk in SE side 9" Elm NE 9.23'
County Survey Disk in S side 14" Hard Maple W 32.00'
Post w/sign 1' North
This corner is located by GPS reference stations "Kautz A & B"

Corner History:

11-5-1981 County Surveyor found stub of old post . Set 1/2" rod on south side of post stub to hold location.

11-25-1981 County Surveyor set cast iron cap on telspar pipe. The corner is 9' west of the N-S fence and 16' south of the corner post to fences NNE and south.

7-2-2001 County Surveyor found cast iron cap on telspar pipe in good condition.

3-1-2010 Rudy Martin, MN/DOT Crew Chief, found CIC on Telspar pipe in good condition.