Certificate of Location of Government Corner

ID#: 850906 **Description:** 1/4 SEC COR 8 9 85 **Date Set:** 8/27/79 **County:** Olmsted

Section: 09 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fences N-E-W
County Survey Disk in SW side 10" Black Oak with blaze WNW 66.35'
County Survey Disk in NE side 14" Black Oak with blaze NW 62.01'
Sign on CP 2' N
This corner is located by GPS reference stations "EMB & Banitt"

Corner History:

6-1854 Gov't Notes: John Cushing, Deputy Surveyor. North between sections 8 and 9. 40.0 chs. Set quarter section post. RPs- 8" aspen N52°E 12 links, 6" aspen S72°W 4 links We could find no other survey records on this corner.

8-20-1979 County Surveyor found a 3/4" square by 10" drag tooth driven in clay and also a hole of 2" to 3" diameter running well into clay 1.0' west of drag tooth. There was a large boulder over the drag tooth, but most of it was in the fill and we couldn't tell if it had been set or just pushed in by the corner post. Set CIC on a 5' pipe (square) over drag tooth.

3-9-2001 County Surveyor found cast iron cap on telspar pipe up 0.2' in good condition.