Certificate of Location of Government Corner

ID#: 851105 **Description:** SEC COR 10 11 14 15 85 **Date Set:** 1/30/2006 **County:** Olmsted

Section: 11 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' north of E-W fence
Post w/sign 2' N
This corner is located by GPS reference stations "Stagecoach A & B"

Corner History:

1854 Gov't Notes: 80.0 set corner post to sections 10-11-14-15 and made mound, trench, and drove charred stake.

Pioneer references: West to centerline trail 181.0',south to centerline trail 203.5'

12-1894 W.Fraser Pg.556 No.513; Found stake in center of mound with pile of stones aound it with glass avered by old settlers to be where original stake stood. 16 east set stone, 16 west set iron rod, 16 south set iron rod, 16 center set iron.

1-1897 W.Fraser Pg.604 No.594; Found corner Pg.556. Measured east and north.

9-1939 J.Kerr Bk16 Pg.7; Found corner stake, stones, and glass. Set 1 3/8"x6' stage coach axle as corner up about 1'. Found 1/16 iron south and 1/16 iron center and found 1/16 stone east and stones at N 1/4 14.

9-1964 County Surveyor accepted stage coach axle 1 3/8"x6' as better than CIM as corner.

8-8-2001 County Surveyor found stage coach axle in good condition.

12-10-2002 County Surveyor found stage coach axle up 0.8' in good condition.

1-30-2006 County Surveyor found stagecoach axle in good condition up 0.8', took local ties and cut off 0.9' of axle. Set 5 1/2' telspar pipe w/CIC over top of axle up 0.3'. Monument falls 1' north of E-W fence. Sign & post 2.0' north.