Certificate of Location of Government Corner

ID#: 852306 **Description:** 1/4 SEC COR 22 23 85 **Date Set:** 11/13/1969 **County:** Olmsted

Section: 23 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 71.5' NW of centerline CR 131 on curve
1" vent pipe by gas pump NNE 90.2'
Filler pipe by gas pump NNE 85.0'
Boat spike in 4' Elm WNW 71.6'
Center of 28" Burr Oak N 162.0'
Center of 30" Elm N 75.3'
This corner is located by GPS reference stations "Zemke A & B"

Corner History:

1854 Gov't Notes: John Cushing, 40.0 set quarter section post. RP- 13" oak N20 E 210 links and made trence.

1-1858 T. Hunter Pg. 48 No. 70 shows 1/4 post.

12-1894 W. Fraser Pg. 558 No.513; Found stone set as corner and left as found.

4-1948 J.Kerr Bk.37 Pg.23; Found corner, run line west and set center 22. Corner is pipe in garden.

11-13-1969 County Surveyor set CIM over 1"x22" iron below ground 12" with stones and junk.

3-28-1977 County Surveyor found cast iron monument down 1' in good condition.

6-1978 County Surveyor set a survey marker sign and post 1' north of the CIM.

2-5-2001 County Surveyor found a new small tree planted on top of corner. Post w/sign is gone.

3-16-2012 County Surveyor found CIM down 0.8' in good condition. Measured the location using reference stations Zemke A & B. Removed CIM to search for bottle with note referred to in 1969 field notes. Found bottle in good condition. Did not search for the 1"x22" iron below the CIM because a tree and its roots are obstructing the corner.