# Certificate of Location of Government Corner

**ID#:** 852405 **Description:** SEC COR 23 24 25 26 85 **Date Set:** **County:** Olmsted

**Section:** 24 **Township:** 108N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls in line with fence north
Post w/sign 2' South
This corner is located by GPS reference stations "Regnier A & B"

**Corner History:**

1854 Gov't Notes: Cushing, 80.00 set post and cor sec 23-24-25-26 from which a white oak 12 in. 13 N 77 E 23 links. Aspen 17 in. 13 S 41 W 38 links. Elm 14 in. 13 N 45 W 80 links. White Oak 10 in. 13 S 40 E 85 links.

4-1871 Perry by Hunter (P.181 No.192 S.24) W. McCullough found stake tested by witness trees. Meas east 39.68, meas north 40.00 set M&L 20.00.

1-1892 Thos Fraser (P.468 No.450 S.24) F. Van Horn found unmarked stake tested SE and SW B trees. New B tree 6" White Oak S45°W 56-1/4 links 37.1'. Meas east 79.27-1/2 5232.15'. Meas north 39.78-1/3 2625.7' to stake set M&L.

6-1899 Robert Fraser (P.643 No.579 S.25) Stevens, Holmes, Tilleson, and others found old stake and new stake evidently nearby. South meas 39.76 with stakes driven on line at porp distances not given 2624.16 to stake found.

11-1887 Hunter (P.424 No.413 S.26) J. Rivelle, M. Patterson, corner finally found after meas from 1/4 24-25 west 39.68 chs 2618.9', found remains of original stake. Set new stake well down Mr. M.L. Patterson agreed to set stone by stake as witness. Found rotted stumps of SE and SW B trees. 16 west set stake M&L 20.53 1355.0'

6-1940 J. Kerr (B.17 P.1 and 2 S.24) W.L. Moth failing to find 1/4 23-24, found and witnessed by Co. H.D. B.86 P.78 run and meas line between sections 23 and 24. Used corner post at NW cor 24, noted stake at fence corner at SW cor 24. Meas 5248.2 set 3/4" iron M&L 2624.1.

12-3-1973 County Surveyor found 1" square hollow iron set by McGhie 1967 about 1' west of corner post now completely gone. Below ground wired up post top lying NE of iron. Dug entire area found a hole but no stone or post stub.

1-22-2003 County Surveyor found 1" square pipe up 1.0' in good condition. Drove pipe down and set cap #15809 in pipe at surface. Steel post 0.8' South.