Certificate of Location of Government Corner

ID#: 852706 **Description:** 1/4 SEC COR 27 28 85 **Date Set:** 11/9/00 **County:** Olmsted

Section: 27 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.4'
The corner falls 40' north of 4' wide ditch in ravine running E-W
Post with sign 1' west
This corner is located by GPS reference stations "Presnall I & II"

Corner History:

1854 Gov't Notes: Cushing, 40.00 set 1/4 section post from which a Butternut 12 in. S66 E43 links.

1863 P. C. Compton (P.70 No.99) used corner to set stone and glass and cinders at center 28. Corner now in center of big farm (over 400 acres) would require setting on N-S section line M&L or inters by E-W 1/4 line if could be established further west from center 28.

4-25-2000 County Surveyor visited corner location. Found nothing.

8-31-2000 County Surveyor set 120d at M & L

11-9-2000 County Surveyor searched for any occupation line in area of corner. Found no fence or evidence. Dug small area and found clay to be only 0.3' deep. Set telspar pipe w/CIC up 0.4' packed with limestones at lost position from GPS traverse.

3-19-2012 County survey crew found cast iron cap on square pipe in good condition